






SECTION A-A
SCALE 1:10




ONLY THE 3 HOLES Ø40 H7 AND THE 2 HOLES 5H7 HAVE TO BE MACHINED AFTER WELDING
THEY ARE LOCATED FROM THE ACTUAL POSITIONS OF HOLES A, B, C



The diagram shows three views of a mechanical part:

- Front View (Top):** A rectangle with a total width of 20 and a total height of 20. A horizontal line is drawn at a height of 12 from the bottom. A vertical line is drawn at a distance of 6 from the left edge, extending from the 12-height line to the top. A section line (two parallel lines with a 45-degree break line) is shown on the right side of the part, indicating a section cut.
- Top View (Bottom):** A rectangle with a total width of 20 and a total depth of 12. A horizontal line is drawn at a distance of 6 from the left edge, extending across the entire depth. A vertical line is drawn at a distance of 6 from the left edge, extending from the 12-depth line to the top. A section line is shown on the right side of the part, indicating a section cut.
- Side View (Left):** A rectangle with a total width of 20 and a total height of 20. A horizontal line is drawn at a height of 12 from the bottom. A vertical line is drawn at a distance of 6 from the left edge, extending from the 12-height line to the top. A section line is shown on the right side of the part, indicating a section cut.

Dimensions are given in millimeters (mm). The scale is 2:1. The part is labeled "MILITARY PARTS".

[illegible]